

i'd like to inform you, that i'm absolutely surprised about the paint and sandblasting work of the Hvide Sande shipyard!

In 2018 your shipyard/ paint shop sandblasted the bottom and put on one layer on welding seams, two layers completely and antifouling.

Since that work we use less fuel and the anodes are still fine. We use them on the hull a year longer again, so the third year now. Before we need to change them annual!

In each year we save 1300€ for the anodes.

This year your shipyard dismantled, sandblasted and painted our old bathroom on board.

After that a new bathrom incl. floor- and wallheating has been installed.

The feedback from crew and surveyors is awesome. Great job!

Best regards,

Robert, SC-58 "Heimdall"